

# CERTIFICATE OF CONFORMITY

## Product Certification Scheme: Class 1

This Certificate is issued to:

ASSOCIATED ENTERPRISES (S) PTE LTD  
Blk 28, #01-173 Sing Ming Drive  
Singapore 575702

FOR

**Product** : *Breeching Inlet*  
**Brand** : *AE*  
**Model** : *refer to Appendix*  
**Country of Origin** : *Singapore*  
**Product Details** : *refer to Appendix*


which has complied with the requirements of the scheme based on the following:

### STANDARD(S)

BS 5041 Part 3 : 1975

### TEST REPORT(S)

G169180/PT  
G169610/PT



**Sze Thiam Siong (Mr)**  
General Manager  
SETSCO Services Pte Ltd

Certificate No	Date of Original Issue	Date of Last Revision	Date of Expiry
FSP-2010-0010	20/12/2010	13/09/2013	19/12/2016



This Certificate is part of full report and should be read in conjunction with it. This Certificate remains the property of SETSCO Services Pte Ltd (SETSCO) and shall be returned upon request. The use of this Certificate is subjected to the terms and conditions of the SETSCO Product Certification Scheme. The manufacturer is solely responsible for the compliance of any product that has the same designation as the product type-tested. Persons relying on this Certificate should verify its validity by checking SETSCO website at [www.setsco.com](http://www.setsco.com).



The use of the SAC accreditation mark indicates accreditation in respect of those activities covered by the accreditation certificate number PD-2010-10.

# APPENDIX TO CERTIFICATE NO. FSP-2010-0010


## ASSOCIATED ENTERPRISES (S) PTE LTD

### 4-Way Breeching Inlet

Model	Description
Fig.135	150mm Flanged Type 4-Way Breeching Inlet

### 2-Way Breeching Inlet

Model	Description
Fig.136	100mm Flanged Type 2-Way Breeching Inlet



**Sze Thiam Siong (Mr)**  
General Manager  
SETSCO Services Pte Ltd

<b>Certificate No</b>	<b>Date of Original Issue</b>	<b>Date of Last Revision</b>	<b>Date of Expiry</b>
FSP-2010-0010	20/12/2010	13/09/2013	19/12/2016

Amendments or additions to this appendix other than those authorized by SETSCO render the appendix invalid.