

CERTIFICATE OF CONFORMITY

This Certificate is issued to

ASSOCIATED ENTERPRISES (S) PTE LTD
Blk 28 Sin Ming Drive
#01-173
Singapore 575702

For Product Certification Scheme: Class 1

Product : **Mobile Fire Extinguisher**
Brand : **PROTEC**
Model : **Refer to Appendix**
Country of Origin : **Singapore**
Product Details : **Refer to Appendix**

which has complied with the requirements of the scheme based on the following:

STANDARD(S)	TEST REPORT(S)
BS EN 1866-1: 2007	Test Report No.: 275597
	Test Report No.: 282995
	Test Report No.: 282994
	Test Report No.: 282992
	Test Report No.: 282993



Sze Thiam Siong (Mr)
General Manager
SETSCO Services Pte Ltd
18 Teban Gardens Crescent
Singapore 608925

Certificate No
FSP-2013-0139

Date of Issue
05/06/2016

Date of Expiry
04/06/2019



This Certificate is part of full report and should be read in conjunction with it. This Certificate remains the property of SETSCO Services Pte Ltd (SETSCO) and shall be returned upon request. The use of this Certificate is subjected to the terms and conditions of the SETSCO Product Certification Scheme. The manufacturer is solely responsible for the compliance of any product that has the same designation as the product type-tested. Persons relying on this Certificate should verify its validity by checking it at www.setsco.com

The use of the SAC accreditation mark indicates accreditation in respect of those activities covered by the accreditation certificate number PD-2010-10.





CERTIFICATION
BODY

Appendix

Certificate No: FSP-2013-0139

Date of Issue: 05 Jun 2016

Product Details

Model No.	Type	Capacity	Fire Rating
PRO-50-MF	Foam (Stored Pressure)	50 Litre	IV B
PRO-100-MF	Foam (Stored Pressure)	100 Litre	IV B
PRO-25-MDC	ABC Powder (Stored Pressure)	25 KG	II B
PRO-50-MDC	ABC Powder (Stored Pressure)	50 KG	IV B
PRO-100-MDC	ABC Powder (Stored Pressure)	100 KG	IV B

Sze Thiam Siong (Mr)
General Manager
SETSCO Services Pte Ltd
18 Teban Gardens Crescent
Singapore 608925

Amendments or additions to this appendix other than those authorized by SETSCO render the appendix invalid.